## Palmer Municipal Airport **2001 Pavement Condition Index Values** Taxiway A [100-01] Section 1 Runway 15-33 Runway 9-27 Runway 15-33 PCI = 68[6100-01] [6200-01] [6100-02] Section 1 Section 2 PCI = 62PCI = 62PCI = 6815 North Taxiway South Taxiway Taxiway B Taxiway B [400-01][300-01] [200-02] [200-01] PCI = 77PCI = 83Section 2, PCI = 65Section 1, PCI = 67General Transport Apron Crossover A and B Lots [4100-01] Taxiway [4200-01] PCI = 79[500-01] PCI = 77**Palmer Airport** PCI = 67C Lot D Lot **PCI** Values [4300-01] [4400-01] **General Recommendations** 85 - 100 Preventative Maintenance PCI = 69PCI = 70Runway 9-27 70 - 84 Preventative/Corrective Maintenance Taxiway A Corrective Maintenance/Overlay [6200-01] 55 - 59 Overlay/Reconstruction [100-02] PCI = 6240 - 54 Reconstruct Section 2 25 - 39 Reconstruct PCI = 5410 - 24 Reconstruct 0 - 9 Reconstruct Minimum PCI for Runway = 70 Minimum PCI for Taxiways and Aprons = 60 [ ] Branch-Section Identifier 500 1000 1500 2000 Feet Airport Code: PAQ Site Number: 50584.\*A

Map Compiled August 16, 2001









